



# SERVICE BULLETIN

<b>Classification:</b> EL92-015	<b>Reference:</b> NTB92-104	<b>Date:</b> December 3, 1992
------------------------------------	--------------------------------	----------------------------------

## 300ZX MAIN POWER WINDOW SWITCH INOPERATIVE

<b>APPLIED VEHICLE(S):</b>	1990-92 300ZX (Z32)	
<b>APPLIED VIN(S):</b>	JN1RZ24H(*)PX535102	July 14, 1992
	JN1RZ26H(*)PX535129	-same-
	JN1CZ24H(*)PX535111	-same-
	JN1RZ27H(*)PX002199	-same-

### SERVICE INFORMATION

On some 300ZX vehicles, customers may complain that the Main Power Window Switch is not operating properly.

To resolve this complaint, a Countermeasure Main Power Window Switch is available. The Countermeasure Switch is an optimized design which utilizes a dust cover to limit intake of dust particles into the switch assembly.

### SERVICE PROCEDURE

Remove the original Main Power Window Switch and replace it with the Countermeasure Unit. Refer to page BF-20 graphic "L" of the appropriate service manual for additional service information.

### PARTS INFORMATION

DESCRIPTION	NEW PART #/PFP	FORMER P/N
Main Power Window Switch	25401-37P11	25401-37P10

### CLAIMS INFORMATION

OPERATION	OP CODE	PNC	CS	CT	FRT
Rpl Power Window Main Switch	RK10AA	25750	4P or 4Q	33	0.3 hr