



SERVICE BULLETIN

Classification: BF92-002	Reference: NTB92-012	Date: February 27, 1992
-----------------------------	-------------------------	----------------------------

300ZX POWER WINDOW JUDDER

APPLIED VEHICLE(S): 1990-91 300ZX(Z32)

SERVICE INFORMATION

On some 300ZX vehicles, customers may complain of a "judder," when raising or lowering the power door windows. If this incident has occurred, a countermeasure power window regulator assembly is available to resolve the customer's concern.

Parts Information

DESCRIPTION	PART NUMBER
Regulator Ass'y, Door Window, RH	80720-30P11
Regulator Ass'y, Door Window, LH	80721-30P11

Claims Information

OPERATION	OP CODE	PNC	CS	CT	FRT
Repl. Window Regulator Ass'y.	UH22AA	80700	3G	31	1.3 hrs.